

Window Schedule and Product Data

Synthetic window schedule with fictional product performance

Project	Redmond Living Room Window Demo	Project ID	DEMO-RED-001
Address	12345 NE Example Street, Redmond, WA 98052	Sheet	A-601
Revision	A	Date	July 26, 2026

Window schedule

ID	Room	Type	Product size	Sill	U-factor	Safety glass
W-01	Living room	Fixed picture	33" x 22"	60"	0.28*	No*
W-02	Living room	Fixed picture	33" x 22"	60"	0.28*	No*

* Synthetic value; not supported by authentic manufacturer or certification evidence.

Fictional product

Manufacturer	DemoView Windows
Model	DV-FX-3322
Operation	Fixed picture
Frame	Vinyl; nail-fin installation
Glazing	Dual-pane low-e; non-tempered (synthetic)
Nominal size	33 in wide x 22 in high
Suggested rough opening	33.5 in wide x 22.5 in high
U-factor	0.28 (synthetic)
SHGC	0.30 (synthetic)
Certification	None - demo artifact

Evidence limitations

Requirement / evidence	Status	Revision A note
Manufacturer identity	PARTIAL	Fictional brand/model
NFRC certification	MISSING	No authentic label or directory record
Installation instructions	MISSING	No manufacturer detail provided
Safety glazing analysis	PARTIAL	No nearby door/stair reported; field conditions unverified
Energy-code applicability	UNKNOWN	Ruleset and compliance path not evaluated in this package

Conceptual Product Detail

Diagrammatic only - not a manufacturer installation instruction

DEMO-RED-001 | Sheet A-601 | Revision A | July 26, 2026

Conceptual assembly

The fictional product is represented as a vinyl fixed window with a nail fin. No sill-pan, flashing-tape sequence, head flashing, sealant compatibility, drainage path, or weather-resistive-barrier integration is specified in Revision A.

Layer / component	Revision A evidence
Interior finish	Not specified
Wood framing	Existing size/spacing unknown
Rough opening	Suggested dimensions only
Window attachment	Nail fin stated; fastener schedule missing
Flashing membrane	Missing
Weather-resistive barrier	Existing condition unknown
Wood siding repair	Scope stated; construction detail missing
Exterior sealant	Missing

REVISION A INTENTIONAL OMISSION

A coordinated flashing/WRB installation detail must be supplied in Revision B. The product should classify this as missing evidence, not invent an installation sequence.